



Efflorescence

Efflorescence is a whitish powder-like deposit, common on concrete and masonry products, which normally will disappear over time with weathering. Although it may present an aesthetic concern, efflorescence will not affect the structural performance of pavers or wall systems. Efflorescence is a natural occurrence for which EP Henry accepts neither responsibility nor liability. Contact your EP Henry Hardscaping Center for additional information and a copy of the Interlocking Concrete Pavement Institute (ICPI) publication [“Managing Efflorescence”](#).